





[illegible][illegible]

BOTTOM VIEW




POWER SUPPLY WITH BATTERY BACKUP




METER LEDS


When on battery, LEDS are off.




PARTS LAYOUT




BOTTOM VIEW




LABEL
(MAKE 1 FOR
DRILLING AND FILING,
2ND FOR FINISH)



LABEL
(1 WILL DO HERE)








PRINTED LABEL
IS SPRAYED WITH
CLEAR COAT AND
WRAPPED
AROUND PANELS

METER
WRAPPED
TO KEEP
LIGHT OUT
OF CABINET

TRANSPARENT
TAPE PROTECTS
METER FROM
ADHESIVE. MAKES
REMOVAL EASY.

LEDs



TERMINAL STRIP
FOR TRANSFORMER
OUTPUTS AND METER
LED SUPPLY

TRANSPARENT
TAPE IS FOLDED ON
METER AND FACE PLATE
BEFORE APPLYING
ADHESIVE

