

C	F	Ohms	C	F	Ohms
90.0	194.0	918.2	97.0	206.6	743.0
90.1	194.2	915.3	97.1	206.8	740.8
90.2	194.4	912.6	97.2	207.0	738.7
90.3	194.5	909.8	97.3	207.1	736.5
90.4	194.7	907.1	97.4	207.3	734.3
90.5	194.9	904.3	97.5	207.5	732.2
90.6	195.1	901.5	97.6	207.7	730.0
90.7	195.3	898.7	97.7	207.9	727.8
90.8	195.4	896.0	97.8	208.0	725.6
90.9	195.6	893.2	97.9	208.2	723.5
91.0	195.8	890.4	98.0	208.4	721.3
91.1	196.0	887.7	98.1	208.6	719.1
91.2	196.2	885.1	98.2	208.8	717.1
91.3	196.3	882.4	98.3	208.9	715.0
91.4	196.5	879.7	98.4	209.1	712.9
91.5	196.7	877.1	98.5	209.3	710.8
91.6	196.9	874.4	98.6	209.5	708.7
91.7	197.1	871.7	98.7	209.7	706.6
91.8	197.2	869.0	98.8	209.8	704.5
91.9	197.4	866.3	98.9	210.0	702.4
92.0	197.6	863.7	99.0	210.2	700.3
92.1	197.8	861.0	99.1	210.4	698.2
92.2	198.0	858.5	99.2	210.6	696.2
92.3	198.1	855.9	99.3	210.7	694.2
92.4	198.3	853.3	99.4	210.9	692.2
92.5	198.5	850.8	99.5	211.1	690.2
92.6	198.7	848.2	99.6	211.3	688.1
92.7	198.9	845.6	99.7	211.5	686.1
92.8	199.0	843.0	99.8	211.6	684.1
92.9	199.2	840.4	99.9	211.8	682.0
93.0	199.4	837.8	100.0	212.0	680.0
93.1	199.6	835.2			
93.2	199.8	832.8			
93.3	199.9	830.3			
93.4	200.1	827.8			
93.5	200.3	825.3			
93.6	200.5	822.8			
93.7	200.7	820.4			
93.8	200.8	817.9			
93.9	201.0	815.4			
94.0	201.2	812.9			
94.1	201.4	810.4			
94.2	201.6	808.0			
94.3	201.7	805.6			
94.4	201.9	803.2			
94.5	202.1	800.8			
94.6	202.3	798.4			
94.7	202.5	796.0			
94.8	202.6	793.6			
94.9	202.8	791.2			
95.0	203.0	788.8			
95.1	203.2	786.4			
95.2	203.4	784.1			
95.3	203.5	781.8			
95.4	203.7	779.5			
95.5	203.9	777.2			
95.6	204.1	774.8			
95.7	204.3	772.5			
95.8	204.4	770.2			
95.9	204.6	767.8			
96.0	204.8	765.5			
96.1	205.0	763.2			
96.2	205.2	761.0			
96.3	205.3	758.8			
96.4	205.5	756.5			
96.5	205.7	754.3			
96.6	205.9	752.0			
96.7	206.1	749.8			
96.8	206.2	747.5			
96.9	206.4	745.3			